
## MARION COUNTY SURVEYOR'S OFFICE



Corner originally set as a post in 1820 by Hendricks with the following witnesses: 22" beech bearing S 54 W 28 links and a 12" ash bearing N 45 E 37 links per Marion County Atlas pg 11. A survey by H.B. Fatout on April 7th, 1852 indicates no stone but the following witnesses: 18" hickory bearing N 14 E 53 and a 24" beech bearing S 57.50 W 72 links per Warren Legal Book pg. 7. Corner referenced by Monroe on 7-10-1951 and called a copper pin. Corner referenced by Wilcoxen on 3-8-76 and called a cut 'x' in concrete. Corner referenced by Gries on 11-30-87 and called a cut 'x' in concrete. Corner referenced by Wilcoxen on 4-28-93 and called a set PK nail. Corner excavated by Kiste on 11-20-1995 and a 1" iron pin was found in concrete. A #205 cast iron Harrison was set in place of the iron pin. Retied 5-8-2000 by Wilcoxen. Retied 9-1-05 by Kiste. Corner excavated 5-14-09 by Wilcoxen and a broken Harrison monument was fd at surface. New Harrison set.

REF.	DISTANCE	DESCRIPTION
1.	87.14'	Rd nail E PwP #255-476 A 6" up
2.	62.55'	Cut 'x' S bolt street signal base
3.	68.95'	Rd nail N PwP #242-476 8" up
4.	80.20'	Cut 'x' W bolt street signal base
5.	65.32'	Cut 'x' E bolt street signal base
6.	63.23'	Cut 'x' S bolt street signal base
7.	54.91'	Top nut of fire hydrant